## 新宿区地盤資料

調査整理番号 023-021

所在地 東京都新宿区新宿二丁目 1 2 - 8 付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

l	深	層	柱	±	色	孔		標準貫入試験										
				質		内 水 位	深	1 ح	0 ci の打	nご 「撃	打擊	Ν						
			状			/		0		数20	打撃回数/貫				N値~	深度図		
				X		測定月日		ı	ł	ı	/ 貫							
	度	厚	図	分	調	百	度	10	20	30	入 量	値	D 10	) 2	20 3	80	40 5	50
	0.50	0.50	AAAA	表土	暗褐													
1							1.15				3 /							
			00000 0000				1.45	1	1	1	30	3						
2							2.15				4 /							
							2.45	1	1	2	30	4						
3				п-4	茶褐		3.15	1	1	1	3 / 30	3						
			WWWW				3.45						$  \  $					
4			88888				4.15	1	2	2	5 / 30	5	4					
5			XXXXX			5.20	4.45 5.15				9							
	5.60	5.10					5.45	2	3	4	/ 30	9						
6							6.15			2,	4		$\mid - \mid - \mid$					
							6.50	1	1	2 / 15	/ 35	3.4						
7							7.15				8 /		$\vdash \setminus$					
					42++		7.45	2	3	3	30	8						
8				粘土	緑青灰		8.15	3	3	4	10 / 30	10	<b>\</b>					
							8.45		Ĭ									
9							9.15	2	2	2	6 / 30	6						
0	10.20	4.60					10.15				22							
l	10.20	4.00				1	10.45	7	7	8	30	22			<b>B</b>			
1			,				11.15				42							
1							11.45	10	13	19	30	42				/	>	
2			;/	シルト混り中砂	暗青灰		12.15		۵	12	28 / 30	28			•			
							12.45	0	0	12		20			\			
33 44 44 4 55 5 5 6 6 6 6 6 6 6 6 6 6 6 6	13.50	3.30	· · · · · · · · · · · · · · · · · · ·				13.15	10	10	10	30 / 30	30				<b>\</b>		
4							13.45				26							
				シルト質細砂	暗青灰		14.15	8	8	10	/ 30	26			<b>/</b>			
5							15.15				21							
-	15.50	2.00				1	15.45	7	7	7	30	21			ø.			
6				1			16.15				8 /			/				
							16.45	2	3	3	30	8						
7				1			17.15	2	2	3	7 / 30	7						
				砂質シルト	暗灰		17.45		Ī	Ĭ		, 						
В							18.15	2	4	6	12 / 30	12		}				
9							18.45				10							
	19.60	4.10					19.15	3	3	4	30	10	1					
0							20.15				11							
							20.45	3	4	4	30	11		<b>†</b>				
1				シルト	暗灰		21.15				14			+-				-

