

所在地 東京都新宿区新宿二丁目5-3付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位／測定月日	標準貫入試験					N 値	N 値～深度図
							深 度	10 cm ごとの打撃回数			打撃回数／貫入量		
								0 〃	10 〃	20 〃			
1	0.90	0.90		埋土	暗褐	5/6 4.05	1.15	2 / 16	2 / 15	4 / 31	3.9		
2				1.46	2 / 14		1 / 6	5 / 30	5				
3				2.15	2 / 15		1 / 5	2 / 11	5 / 31	4.8			
4				2.45	2 / 13		2 / 11	1 / 6	5 / 30	5			
5	4.95	4.05		4.15	5 / 11		5 / 11	4 / 32	13.1				
6			5.15	4 / 11	4 / 5	5 / 30	13	13.1					
7	6.80	1.85	5.47	6.15		13 / 30	1.8						
8			6.45	7.15	1 / 16	1 / 17	2 / 33	1.9					
9	8.60	1.80	7.48	8.15	1 / 15	1 / 16	2 / 31	24					
10			8.46	9.15	6 / 7	11 / 30	27	27					
11			9.45	10.15	7 / 8	12 / 30	29						
12	11.55	2.95	10.45	11.15	8 / 11	10 / 30	41	41					
13			11.45	12.15	12 / 14	15 / 30	46						
14			12.45	13.15	13 / 14	19 / 30	52.5	52.5					
15			13.45	14.15	16 / 18	8 / 28	46						
16			14.43	15.15	14 / 16	16 / 30	39	39					
17			15.45	16.15	13 / 12	14 / 30	41						
18	17.90	6.35	16.45	17.15	12 / 13	16 / 30	9	9					
19			17.45	18.15	3 / 3	3 / 30	9						
20			18.45	19.15	3 / 3	3 / 30	11						
21			19.45	20.15	3 / 4	4 / 30							
			20.45	21.15		12							

