

所在地 東京都新宿区歌舞伎町二丁目22-10付近

標尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値								
							深 度	10 cm ごとの打撃回数			打撃回数 / 貫入量									
								0	10	20										
0.10	0.10			アスファルト	黒	4.25														
0.90	0.80		表土	黒褐																
1.70	0.80		ローム	暗黄褐	1.15		1 / 13	1 / 12	1	3 / 35	2.6									
2.50		1.50			1 / 15		1 / 12	1 / 12	3 / 39	2.3										
3.30		2.54			3.15		1 / 17	1 / 15	2 / 32	1.9										
3.60	2.70	3.47			4.15		1 / 15	1 / 7	1 / 8	3 / 30	3									
4.40			凝灰質粘土	黄灰	4.45															
5.20	1.70	5.15							3 / 30	3										
6.00		5.45			1		1	1	30	3										
6.80		6.15					1 / 15	1 / 17	2 / 32	1.9										
7.60			シルト	暗灰	6.47															
8.40	3.10	7.15					1 / 15	1 / 15	2 / 30	2										
9.20		7.45																		
10.00		8.15					1 / 15	1 / 17	2 / 32	1.9										
10.80			腐植土	暗茶灰	8.47															
11.60		9.15							4 / 30	4										
12.40	1.40	9.45			1		2	1	30	4										
13.20		10.15					5	7	10	22										
14.00			シルト混じり細砂	暗青灰	10.45															
14.80		11.15							32 / 30	32										
15.60	2.00	11.45			10		14	8	30	32										
16.40		12.15						38 / 30	38											
17.20	0.90		砂礫	暗黄灰	12.45	16	12	10	30	38										
18.00			細砂	暗黄灰	13.15															
18.80	0.90	13.45				5	7	10	22											
19.60		14.15				12	21	6	57.7											
20.40		14.41																		
21.20	2.30		細砂	暗青灰	15.15															
22.00		15.45				12	14	21	30	47										
22.80		16.15						38 / 30	38											
23.60	0.90	16.45				13	10	15	30	38										
24.40			砂礫	暗																

