

所在地 東京都新宿区歌舞伎町二丁目42-16付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位／測定月日	10cmごとの打撃回数					N 値	標準貫入試験 N値～深度図
							深 度	10cmごとの打撃回数			打撃回数／貫入量		
								0	10	20			
		0.60	0.60	表土		4.80	1.00	1 / 9	1 / 8	2 / 16	4 / 33	3.6	
1					1.33								
2					2.00		1 / 8	2 / 14	1 / 8	4 / 30	4		
3				ローム	3.00		1 / 7	1 / 8	2 / 15	4 / 30	4		
4					3.30								
5					4.00					3 / 30	3		
6		5.70	5.10		4.30		1 / 9	1 / 12	1 / 31	3 / 31	2.9		
7				凝灰質粘土	6.00					4 / 30	4		
8				茶灰 褐灰 青灰	6.30		1 / 13	1 / 21	2 / 34	1.8			
9					7.00					5 / 30	5		
10		9.80	4.10	シルト混り砂	7.34				7 / 30	7			
11		10.70	0.90		8.00	1 / 2	2 / 2	3 / 30	23				
12				砂礫	8.30	2 / 2	2 / 2	3 / 30	60				
13					9.00	7 / 8	8 / 8	8 / 30	107				
14				暗灰 緑灰	10.00	14 / 32	18 / 4	50 / 14	83.3				
15					11.00	21 / 34	16 / 5	50 / 15	188				
16					11.25	38 / 32	12 / 2	50 / 12	125				
17		17.30	6.60	礫混り砂	12.00	32 / 38	18 / 4	50 / 14	107				
18					12.14	34 / 21	16 / 5	50 / 15	100				
19					13.00	50 / 8		50 / 8	188				
20		20.18	2.88		13.18				125				
					14.00	21 / 21	29 / 8	50 / 18	83.3				
					14.08								
					15.00								
					15.12								
					16.00								
					16.14								
					17.00								
					17.15								
					18.00								
					18.08								
					19.00								
					19.12								
					20.00								
					20.18								