新宿区地盤資料

調査整理番号 071-018

所在地 東京都新宿区若宮町11-2付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

Ī	深	層	柱	土	色	孔		標準貫入試験																	
			状	質区		内水位/測定月日	深	1 اع 0	0 cm の打 の打 3	擊 数	打擊回数/貫	N			N値~	深度図									
	度	厚	図	分	調	日	度	10	20	30	量	値	D 1	0 <u>2</u>	20 3	80 4	40 5	0							
	1.60	1.60		盛土	暗茶灰		1.15	3	6	8	17 / 30	17		<u></u>											
	2.80	1.20		ローム	茶褐 ~ 茶褐灰		2.15	2	2	3	7 / 30	7													
				粘土	暗茶灰 ~ 茶褐灰		3.15 3.45 4.15	2	1	2	5 / 30 3 3/	5	igg												
	5.50	2.70	0:0:0		7K T40/X	6/12 5.90	4.45 5.15 5.45	1	2	2	5 / 30	5	\vdash												
			0.0.0	粘土混じり砂礫	茶褐灰		6.15	11	16	18	45 / 30 40 /	45					7								
	7.80	2.30		シルト混じり細砂	茶褐灰		7.45 8.15 8.45	18	10	12	20 / 30	20					*								
	9.80		====	砂混じりシルト	黄灰	_	9.15	6	7	8	21 / 30	21			•										
	9.80	0.90				-	10.15 10.45	6	7	8	21 / 30	21													
				·····································	黄灰 電黄灰									11.15 11.45 12.15	7		10 15	25 / 30 39 / 30	25			8	>		
											12.45 13.15 13.45	13	7	13	33 / 30 50	33									
	14.70	4.90					14.15 14.37 15.15	14		2	/ 22 24 /	68.2			- A			•							
	16.50	1.80		シルト混じり細砂	暗灰		15.45 16.15 16.45	3	4	4	11 / 30	11													
	17.80	1.30	====	シルト	淡緑灰	-	17.15 17.45	10	12	13	35 / 30 50	35				•									
				砂礫	暗緑灰		18.15 18.25 19.15	50			/ 10 50 / 10	150						• •							
4	20.40	2.60					19.25 20.15	16	18	16	50 / 30	50						,							
							20.45 21.15		18		50														

_	071-018(カ272) (2/ E 20.4d 2.6d こここ															(2/2)	
E	20.40	• •					20.45	16	18	16	50	50				ľ	-
21		,,,					21.15 21.32	32	7		17	88.2					
22			//	シルト質細砂	暗緑灰		22.15	50			50 / 10	150					
							22.25	50				150					=
E 23	23.23		::;; <u>;</u>				23.15	50 / 8			50 / 8	188					