

所在地 東京都新宿区改代町 3 3 - 1 7 付近

標尺	深度	層厚	柱状図	土質区分	色調	孔内水位 / 測定月日	標準貫入試験					N 値 - 深度図	
							深 度	10 cm ごと の打撃 回数			打撃 回数 / 貫入 量		N 値
								0 10	10 20	20 30			
1	1.40	1.40	盛土		黄褐	1.40	1.15	1	2	1	4 / 30	4	
2			腐植質シルト		暗褐		1.45	1			1 / 31	1.0	
3	3.00	1.60	細砂		暗青灰		2.15	1 / 31			1 / 31		
4	3.90	0.90					2.46						
5			粘土		暗灰		3.15				18 / 30	18	
6							3.45	5	6	7	30	0.9	
7							4.15	1 / 35			1 / 35	1	
8							4.50						
9	5.50	1.60					5.15	1 / 30			1 / 30	1	
10							5.45						
11							6.15				19 / 30	19	
12							6.45	6	5	8	30	78.9	
13							7.15	22	28 / 9		50 / 19	88.2	
14							7.34						
15							8.15	26	24 / 7		50 / 17	100	
16							8.32						
17							9.15	32	18 / 5		50 / 15	100	
18							9.30						
19							10.15	30	20 / 5		50 / 15	107	
20							10.30						
21							11.15	33	17 / 4		50 / 14	100	
22							11.29						
23	11.95	6.45					12.15				15 / 5	50 / 15	
24	12.30	0.35	細砂		黄褐		12.30	35			15 / 5	100	