

所在地 東京都新宿区戸塚町一丁目101-10付近

標	深	層	柱	土	色	孔内水位 ／測定月日	標準貫入試験					N	N値～深度図		
							深	10cmごとの打撃回数			打撃回数／貫入量				
								0	10	20					
尺	度	厚	状	質	調		度	10	20	30		値			
	0.70	0.70		瓦礫	暗茶褐	7/28 1.62						0			
1	1.65	0.95		埋土	暗茶褐		1.15	1/17	1/14		2/31	1.9			
2	2.70	1.05		砂質粘土	暗黒灰		1.46					1.6			
3				硬質シルト	淡緑灰		2.15	1/22	1/16		2/38				
4							2.53						25/30	25	
5							3.15						37/30	37	
6							3.45	7	8	10			42/30	42	
7							4.15						39/30	39	
8	6.50	3.80					4.45	10	12	15			46/30	46	
9				硬質シルト	暗灰		5.15				42/30				
10							5.45	11	14	17			45/30	45	
11							6.15	9	12	18			48/30	48	
12				シルト混り細砂	暗灰		6.45				50/22	68.2			
13							7.15					50/16	93.8		
14	8.65	2.15					7.45					50/8	188		
15				細砂	暗黄灰		8.15				50/12	125			
16							8.45	12	15	18			50/10	150	
17							9.15						50/15	100	
18	10.45	1.80					9.45	15	16	17					
19							10.15	17	22	2					
20							10.37		28/6	50/16					
21							11.15			50/8					
22							11.31								
23							12.15		11/2						
24							12.23								
25							13.15	39							
26							13.27								
27							14.15								
28							14.25								
29							15.15		24/5						
30	15.30	4.85					15.30	26							