

所在地 東京都新宿区西落合一丁目7付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位／測定月日	標準貫入試験				N 値	N 値～深度図	
							深 度	10 cm ごとの打撃数					打撃回数／貫入量
								0 回	10 回	20 回			
						1.90	1.15	2 / 30		2 / 30	2		
1			盛土			1.45					6		
2	2.70	2.70				2.15	6 / 30		6 / 30	6			
3	3.20	0.50	シルト質砂			2.45					14		
4			砂レキ			3.15	14 / 30		14 / 30	14			
5	4.30	1.10				3.45					50		
6			細砂			4.15	50 / 30		50 / 30	50	107		
7	5.80	1.50				4.45	50 / 14		50 / 14	107			
8			微細砂			5.15					150		
9	7.70	1.90				6.15	50 / 15		50 / 15	150	71.4		
10	9.90	2.20	細砂			6.30					78.9		
	10.25	0.35	微細砂			7.15	50 / 21		50 / 21	93.8			
						7.36					93.8		
						8.15	50 / 19		50 / 19	150			
						8.34							
						9.15	50 / 16		50 / 16				
						9.31							
						10.15	50 / 10		50 / 10				
						10.25							