

所在地 東京都新宿区北新宿四丁目10-8付近

標尺	深度	層厚	柱状図	土質区分	色調	孔内水位 / 測定月日	標準貫入試験					
							深 度	10 cmごとの打撃回数			打撃回数 / 貫入量	N 値
								0 ι	10 ι	20 ι		
	1.00	1.00		埋土			1.15			1 / 12	3 / 32	2.8
	1.60	0.60		粘土混り細砂	褐灰		1.47	1	1	12		
	2.70	1.10		ローム質粘土	暗褐灰		2.15				0 / 30	
	2.70	1.10					2.45		自沈			
	3.45			砂礫	褐灰	3.30	3.15				18 / 30	18
	3.45						3.45	6	4	8	30	18
	4.15						4.15				36 / 30	36
	4.45						4.45	10	12	14	30	36
	5.15						5.15				13 / 30	13
	5.45						5.45	4	4	5	30	13
	6.15						6.15				27 / 30	27
	6.45						6.45	7	8	12	30	27
	7.15			硬質シルト	暗青灰		7.15				28 / 30	28
	7.45						7.45	9	9	10	30	28
	8.15						8.15				28 / 30	28
	8.45						8.45	8	10	10	30	28
	9.15						9.15				26 / 30	26
	9.45						9.45	7	9	10	30	26
	10.15						10.15				35 / 30	35
	10.45						10.45	8	13	14	30	35
	11.15						11.15	50			50 / 10	150
	11.25						11.25					
	12.15						12.15	50			50 / 9	167
	12.24						12.24	9				
	13.15			細砂	暗緑灰 暗灰		13.15		23 / 6		50 / 16	93.8
	13.31						13.31	27				
	14.15						14.15		12 / 2		50 / 12	129
	14.27						14.27	38				
	15.15						15.15		18 / 4		50 / 14	107
	15.29						15.29	32				
	16.15						16.15				50 / 20	75
	16.35						16.35	23	27			