

所在地 東京都新宿区荒木町13付近

標尺	深度	層厚	柱状図	土質区分	色調	孔内水位／測定月日	標準貫入試験					N値	N値～深度図
							深 度	10 cmごとの打撃回数			打撃回数／貫入量		
								0 ι	10 ι	20 ι			
0.90	0.90			埋土	茶褐	2.90	1.15	2 / 11	2 / 9	2 / 2	6 / 30	6	
1.45	2 / 11	3 / 9	3 / 3	8 / 30	8								
2.45	2 / 11	2 / 2	12 / 12	32 / 32	5.6								
3.47	2 / 12	2 / 8	2 / 2	6 / 30	6								
4.45	2 / 11	3 / 9	3 / 9	8 / 30	8								
5.45	2 / 12	1 / 8	4 / 30	4									
6.45	1 / 1	1 / 1	2 / 2	5 / 30	5								
7.47	1 / 2	12 / 12	32 / 32	3.8									
8.45	1 / 1	1 / 1	2 / 2	4 / 30	4								
9.45	1 / 2	2 / 2	3 / 3	8 / 30	8								
10.45	2 / 3	3 / 3	3 / 3	8									
11.45	13 / 12	13 / 13	38 / 30	38									
12.39	16 / 24	10 / 4	50 / 24	62.5									
13.36	17 / 27	6 / 1	50 / 21	71.4									
14.33	30 / 8	50 / 18	83.3										
15.43	13 / 15	22 / 8	50 / 28	53.6									
16.40	19 / 19	12 / 5	50 / 25	60									
17.22	50 / 7	50 / 7	214										
17.22													
17.22													