

所在地 東京都新宿区大京町12-49付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔 内 水 位 ／ 測 定 月 日	10 cmごとの打撃数				N 値	標準貫入試験 N 値～深度図	
							深 度	10 cmごとの打撃数					打撃回数／貫入量
								0	10	20			
								0	10	20	30		
1		1.60	埋土		暗灰	9/21 2.65	1.15	1/21	1/14	2/35	1.7		
2		2.60	表土		黒灰		2.15	2/15	1/5	6/30	6		
3			粘土質ローム		暗褐灰	9/21 2.65	3.15	1/11	1/11	1/9	3/31	2.9	
4		4.70		2.10			4.15	1/30	1/30	1			
5			粘土		黄褐	9/21 2.65	5.15	0/20	1/20	1/40	0.8		
6				6.15			0/20	1/16	1/36	0.8			
7				7.15		1/15	1/11	1/9	3/35	2.6			
8				8.15		1/20	1/15	2/35	1.7				
9		8.75		4.05		9.15		26/30	26				
10		10.25		1.50		10.15	7/9	11/30	27				
11			中砂		褐灰	9/21 2.65	11.15	3/4	7/30	14			
12				12.15			5/6	8/30	19				
13		13.65		3.40		13.15	6/8	13/30	27				
14				14.15		3/5	5/30	13					
15			細砂		暗青灰	9/21 2.65	15.15	6/13	17/30	36			
16		15.80		2.15			15.45		50/30	50			
17		16.20	0.40	16.15	8/14	28/30	50						
18		17.55	1.35	17.15	20/19	5/25	60						
		18.20	0.65	18.15	50/5	50/5	300						