

所在地 東京都新宿区大京町 3 付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値	N 値 - 深度図		
							深 度	10 cm ごと の打撃 回数			打撃 回数 / 貫入量				
								0 ι 10	10 ι 20	20 ι 30					
		0.80	0.80	埋土	黒褐	9/14 1.10									
1				腐植質シルト	黒褐		1.15	1 / 20	1 / 20	2 / 40	1.5				
2							1.55								
3							2.35	1 / 30		1 / 30					
4		3.70	2.90				2.65 3.00			0 / 50					
5				凝灰質粘土	乳黄褐 暗褐灰 淡緑灰		3.50	自沈							
6							4.00			0 / 50					
7							4.50								
8							5.00			0 / 50					
9							5.50	自沈							
10							6.15			2 / 30					
11							6.45	0	1	1	30				
12							7.15	1 / 15	1 / 15	2 / 30					
13							7.45								
14							8.15	1 / 20	1	2 / 30					
15				8.45											
16				9.15			4 / 30								
17				9.45	2	1	1	30							
18		10.30	6.60	細砂	暗灰		10.15			18 / 30	18				
19							10.45	4	4	10	30				
20							11.15			28 / 30					
21							11.45	7	10	11	30				
22				微細砂	暗灰 暗緑灰		12.15			47 / 30	47				
23		12.70	2.40				12.45	15	15	17	30				
24							13.15			27 / 30					
25							13.45	10	8	9	30				
26							14.15	13	27	1	21	71.4			
27							14.36								
28		15.36	2.66				6 / 1	50 / 21	71.4						
29															
30							15.15								
31							15.36	17	27						