

所在地 東京都新宿区歌舞伎町二丁目31-16付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値	N 値 - 深度図
							深 度	10 cm ごと の打撃 数			打撃回 数 / 貫入量		
								0	10	20			
		0.40	0.40	盛土									
1							1.15	3 / 30		3 / 30		3	
2							1.45					6	
3				ローム			2.15	6 / 30		6 / 30		2.8	
4							2.45					2	
5							3.15	3 / 32		3 / 32		2.8	
6							3.47					2	
7		5.30	4.90				4.15	2 / 30		2 / 30		2.8	
8				粘土			4.45					2	
9							5.15	3 / 32		3 / 32		6	
10							5.47					34	
11							6.15	2 / 30		2 / 30		62.5	
12		6.90	1.60	有機質粘土			6.45					83.3	
13							7.15	6 / 30		6 / 30		60	
14							7.45					75	
15		8.15	1.25				8.15	34 / 30		34 / 30		100	
16				砂礫			8.45					53.6	
17							9.15	50 / 24		50 / 24			
18							9.39						
19							10.15	50 / 18		50 / 18			
20							10.33						
21							11.15	50 / 25		50 / 25			
22							11.40						
23							12.15	50 / 20		50 / 20			
24							12.35						
25							13.15	50 / 15		50 / 15			
26							13.30						
27		14.43	6.28				14.15	50 / 28		50 / 28			
28							14.43						