

所在地 東京都新宿区歌舞伎町二丁目2-20付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔 内 水 位 ／ 測 定 月 日	10cmごとの打撃回数				打撃回数／貫入量	N 値	標準貫入試験				
							深 度	0	10	20			N 値～深度図				
							度	10	20	30							
	0.50	0.50		埋土	暗褐灰	5.40 ▽	1.15				3 / 30						
1							1.45	1	1	1	1 / 30						
2							2.15				4 / 30						
3							2.45	1	1	2	2 / 30						
4				ローム	暗茶褐		3.15				8 / 30						
5							3.45	2	3	3	3 / 30						
6							4.15				9 / 30						
7							4.45	2	3	4	4 / 30						
8							5.15				7 / 30						
9	6.50	6.00					5.45	2	2	3	3 / 30						
10						6.15				4 / 30							
11						6.45	1	2	1	1 / 30							
12						7.15				3 / 30							
13						7.45	1	1	1	1 / 30							
14						8.15				3 / 30							
15	9.00	2.50				8.45	1	1	1	1 / 30							
16						9.15				50 / 20							
17						9.35	21	29		20 / 25							
18						10.15				15 / 5	50 / 25						
19	11.10	2.10				10.40	17	18									
20						11.15				13 / 30							
21						11.45	4	4	5	5 / 30							
22	12.00	0.90				12.15				17 / 30							
23						12.45	5	4	8	8 / 30							
24						13.15				17 / 30							
25						13.45	4	6	7	7 / 30							
26						14.15				20 / 30							
27						14.45	6	6	8	8 / 30							
28						15.15				18 / 30							
29						15.45	4	8	6	6 / 30							
30						16.15				15 / 30							
31						16.45	4	5	6	6 / 30							
32						17.15				14 / 30							
33						17.45	4	5	5	5 / 30							

