

所在地 東京都新宿区市谷田町三丁目1付近

標	深	層	柱	土	色	孔内水位 / 測定月日	標準貫入試験					N	
							深	10 cmごとの打撃数			打撃回数 / 貫入量		N 値
								0	10	20			
尺	度	厚	状	質	調		度	10	20	30	量	値	
				盛土	暗茶褐	3.50	1.15	1 / 30			1 / 30	0	
1	1.20	1.20					1.45						1
2				有機質粘土	黒褐		2.15	1 / 20	1		2 / 30	2	
	2.65	1.45					2.45						2
3				ローム	茶褐		3.15		2 / 15	1 / 5	4 / 30	4	
	3.50	0.85					3.45	1					4
4							4.15	1 / 25	1 / 15		2 / 40	1.5	
							4.55						1.5
5				凝灰質粘土	黄褐 黄灰 暗褐		5.15	1 / 20	1		2 / 30	2	
							5.45						2
6							6.15				3 / 30	3	
							6.45	1	1	1	3 / 30	3	
7							7.15				3 / 30	3	
	7.60	4.10					7.45	1	1	1	3 / 30	3	
8				粘土混り細砂	暗黄灰		8.15				19 / 30	19	
	8.80	1.20					8.45	1	3	15	30	19	
9				粘土質細砂	暗黄灰	9.15				21 / 30	21		
	9.70	0.90				9.45	6	7	8	30	21		
10				粘土	黄灰	10.15				10 / 30	10		
						10.45	3	3	4	30	10		
11						11.15		21 / 5		50 / 15	100		
						11.30	29				100		
12						12.15		19 / 4		50 / 14	107		
						12.29	31				107		
13						13.15		50 / 9		50 / 9	167		
				砂礫	暗灰	13.24					167		
14						14.15				50 / 10	150		
						14.25	50				150		
15						15.15		50 / 3		50 / 3	500		
						15.18					500		
16						16.15		50 / 5		50 / 5	300		
	16.20	5.25				16.20					300		