

所在地 東京都新宿区山吹町 3 3 2 - 1 付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値	N 値 - 深度図
							深 度	10 cm ごとの打撃回数			打撃回数 / 貫入量		
								0	10	20			
0.80	0.80			盛土	暗褐	2.40	1.15			0 / 30	0		
1.15			自沈		0 / 30								
1.45			自沈		0 / 35								
2.15			自沈		1 / 30		1						
2.50	1.70		粘土質細砂	暗褐	3.15		1 / 30	1					
3.40	0.90		粘土	淡黄灰	3.45								
3.70	0.30				4.15			50 / 20	75				
					4.35		27	23					
					5.15			18 / 3	50 / 13	115			
					5.28		32						
					6.15		50		50 / 10	150			
					6.25								
					7.15		12 / 1	50 / 11	136				
					7.26	38							
					8.15	50 / 8		50 / 8	188				
					8.23								
					9.15		10 / 2	50 / 12	125				
					9.27	40							
					10.15		18 / 9	50 / 19	78.9				
					10.34	32							
					11.15		20 / 5	50 / 15	100				
					11.30	30							