

所在地 東京都新宿区早稻田鶴巻町110-23付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値	N 値 - 深度図
							深 度	10 cm ごと の打撃回数			打撃回数 / 貫入量		
								0	10	20			
				埋土	褐								
1	0.60	0.60		有機質粘土	黒灰		1.15	1 / 30		1 / 30			
	1.15	0.55					1.45						
2				凝灰質粘土	褐 黄灰 褐灰		2.15	1 / 30		1 / 30			
							2.45						
3	3.20	2.05					3.15			15 / 30			
				砂礫	黄褐		3.45	3	5	7	30	15	
4	3.90	0.70		礫混り粗中砂	緑灰		4.15			19 / 30			
	4.40	0.50					4.45	6	6	7	30	19	
5							4.45						
							5.15	50 / 9		50 / 9		167	
6							5.24						
							6.15		21 / 5	50 / 15		100	
7				砂礫	暗青灰		6.30	29					
							7.15	50 / 4		50 / 4		375	
8							7.19						
							8.15		12 / 3	50 / 13		115	
9							8.28	38					
							9.15		20 / 6	50 / 16		93.8	
	9.31	4.91					9.31	30					