## 新宿区地盤資料

調査整理番号 099-088

所在地 東京都新宿区早稲田鶴巻町559付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

標	深	層	柱	土	色	孔							標準貫入試験
尺	度	厚	状図	質 区 分	調	,内水位/測定月日	深度	□ 0 ~	10 ≀	数	打撃回数/貫入量	N 値	N値~深度図
- 1	2.40	2.40		埋土	暗褐灰暗褐		1.15	1 1 11	1	2 / 12	4 / 31 4 / 32		3.8
3	3.90	1.50		D-A	暗褐		3.15 3.48 4.15		2 / 13	2	5 / 33		1.5
1 2 3 4 5 6 7 9 10			\(\text{X}\times\t			6.70	4.45 5.15 5.45 6.15 6.34		16	19 28 / 9	30 48 / 30 50 / 19		31 48 3.9 3.2 60
- 7 - 8 - 9				砂礫	茶褐茶		7.15 7.32 8.15 8.40 9.15		17	26 / 7 17 / 5	50 /17 50 /25		60
- 10	10.37	6.47	0.0000000000000000000000000000000000000				9.35		25	7 / 2	50 / 22	68	75