

所在地 東京都新宿区余丁町 1 2 - 4 付近

標	深	層	柱	土	色	孔内水位 / 測定月日	標準貫入試験					N	N値 - 深度図	
							深	10 cmごとの打撃数			打撃回数 / 貫入量			
								0	10	20				
尺	度	厚	状	質	調		度	10	20	30	量	値		
1			埋土	暗褐		7/11 4.90	1.15	1 / 12	1	1 / 8	3 / 30	3		
2							2.15			2 / 11	4 / 31	3.9		
3	2.80	2.80					腐植土質ローム	黒褐	3.15			3 / 30		3
4									3.45	1	1	1		3 / 30
5			4.15	1 / 17	1 / 13				2 / 30	2				
6	5.90	3.10	4.45								1			
7			凝灰質粘土	黄灰褐 乳黄灰褐	5.15		1 / 30		1 / 30	1				
8					5.45						1.8			
9					6.15		1 / 18	1 / 15	2 / 33	1.0				
10	8.30	2.40			7.15		1 / 31		1 / 31	1.9				
11			砂質凝灰質シルト	乳黄灰褐	7.46					4				
12					8.15		1 / 17	1 / 15	2 / 32	4.8				
13					8.47					10				
14					9.15		1	1	2	14				
15			凝灰質細砂	暗黄褐	9.45					17				
16					10.15		1	2 / 11	5 / 31	24				
17					10.46					20				
18					11.15		3	3	4	17				
19			細砂	暗灰	11.45					55.6				
20	12.30	4.00			12.15		4	5	5	60				
21					12.45				75					
22					13.15	7	7	10	70.9					
23					13.45				6					
24					14.15	6	7	7	6					
25	15.20	2.90			14.45				6					
26					15.15	5	5	7	6					
27					15.45				6					
28					16.15	16	17	17 / 7	50 / 27	6				
29					16.42					6				
30					17.15			14 / 5	50 / 25	6				
31					17.40	18	18		6					
32					18.15	23	27		50 / 20	6				
33					18.35					6				
34					19.15			6 / 2	52 / 22	6				
35	19.95	4.75			19.37	21	25		6					
36					20.15	2	2	2	6 / 30	6				
37					20.45					6				
38					21.15	1		2	5	6				

