

所在地 東京都新宿区百人町三丁目3 - 1 1 付近

標高	深度	層厚	柱状図	土質区分	色調	孔内水位 / 測定月日	標準貫入試験					N 値	N 値 - 深度図	
							深さ	10 cm ごと の打撃回数			打撃回数 / 貫入量			
								0	10	20				
尺	度	厚	図				度	10	20	30		値		
	0.80	0.80		盛土	暗褐	9/7 5.20 	1.15				8 / 30	8		
1				茶褐	1.45								6	
2					2.15		2	2	2	6 / 30	6			
3					2.45									
4					3.15						4 / 30	4		
5					3.45		1	2	1	30	3			
6					4.15						3 / 30	3		
7	6.60	5.80		黄褐灰	4.45		1	1	1	30	3		3	
8					5.15						3 / 30	3		
9					5.45		1	1	1	30	3			
10					6.15						3 / 30	3		
11	8.40	1.80		黄褐 暗灰	6.45		1	1	1	30	3		3	
12					7.15		1 / 20	1 / 15	2 / 35	1.7				
13					7.50									
14					8.15					8 / 30	8			
15					8.45		1	1	6	30	8			
16					9.15			11 / 5	50 / 25	60				
17					9.40	20	19	3	65.2					
18					10.15			12 / 3	50 / 23	65.2				
19					10.38	15	23			44				
20					11.15				44 / 30	44				
21			11.45	11	17	16	55.6							
22			12.15			17 / 7	50 / 27	188						
23			12.42	13	20			500						
24			13.15			50 / 8	50 / 8	300						
25			13.23											
26			14.15	50 / 3		50 / 3								
27			14.18											
28			15.15	50 / 5		50 / 5								
29			15.20											
30	16.20	7.80		青灰	16.15			12 / 3	50 / 23	65.2				
31	16.38	0.18			16.38	17	21							