

所在地 東京都新宿区北新宿一丁目27-12付近

標高	深度	層厚	柱状図	土質区分	色調	孔内水位／測定月日	標準貫入試験					N値	N値～深度図
							深さ	10cmごとの打撃回数			打撃回数／貫入量		
								0	10	20			
尺	度	厚	図				度	10	20	30		値	
		0.80	0.80	盛土	暗褐色								
1													
2								2.15			4 / 30		
3								2.45	2	1	1		
4				ローム	茶褐色			3.15			5 / 30		
5						10/11		3.45	2	2	1		
6						5.15		4.15			4 / 30		
7						4.45		4.45	2	1	1		
8				火山灰質粘土	茶褐色			5.15			6 / 30		
9						5.45		6.15	2	2	2		
10						6.45		7.15			6 / 30		
11				砂礫	茶褐色			7.45	2	2	2		
12						7.70		8.15			3 / 30		
13				砂混じり粘土	茶褐色			8.45	1	1	1		
14						9.10		9.15			29 / 30		
15				砂礫	茶褐色			9.45	9	8	12		
16						10.15		10.45	13	15	17		
17				シルト混じり細砂	茶褐色			11.15			38 / 30		
18						11.45		12.15	12	12	14		
19				砂礫	茶褐色			12.44			17 / 29		
20						13.15		13.45	15	18	9		
21				シルト混じり細砂	茶褐色			14.15	13	9	7		
22						14.45		15.15			29 / 30		
23				砂礫	茶褐色			15.45	8	10	12		
24						16.15		16.44			30 / 30		
25				シルト混じり細砂	茶褐色			17.45	4	5	7		
26						17.50		18.15			16 / 30		
27				砂礫	茶褐色			18.45			20 / 29		
28						19.15		19.45	14	16	9		
29				シルト混じり細砂	茶褐色			20.15			43 / 30		
30						20.45		21.15	13	14	16		
31						21.45			6	7	14		
32						22.15					27 / 30		
33						23.15					33 / 30		
34						24.15			10	10	13		
35						25.15					47 / 30		
36						26.15			11	15	21		
37						27.15					20 / 30		

