

所在地 東京都新宿区北新宿二丁目 1 9 - 1 1 付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	10 cmごとの打撃回数				N 値	標準貫入試験 N 値 - 深度図
							深 度	10 cmごとの打撃回数				
								0	10	20		
	0.50	0.50		表土	暗褐	1.65						
1	1.20	0.70		ローム質粘土	茶灰 茶褐		1.15			6 / 30	6	
2				砂礫	褐灰		1.45	2	2	2	57.7	
							2.15	17	21	12 / 6	50 / 26	
3							2.41					
							3.15				48 / 30	
4	3.80	2.60		シルト混じり砂礫	暗青灰		3.45	13	17	18	48	
							4.15				46 / 30	
							4.45					
5							5.15				50 / 30	50
						5.45	14	16	20	30		
6	6.50	2.70				6.15				47 / 30	47	
7				礫混じり細砂	暗青灰	6.45	14	16	17	47		
						7.15				26 / 30	26	
						7.45	7	9	10	30 / 30		
8	8.50	2.00				8.15				50 / 22	68.2	
				8.37	9	11	2					
9				微細砂	緑青灰	9.15			22 / 4	50 / 14	107	
						9.29	28					
10	10.27	1.77				10.15				19 / 2	50 / 12	125
						10.27	31					