## 新宿区地盤資料

調査整理番号 142-040

所在地 東京都新宿区北新宿二丁目13-14付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

位置的報については、ののなどの位置と小したものとなりよう。															
標	深	層	柱	土	色	孔 内						標準貫入試験			
			状	質		水位	深	1 と 回	0 cm の打	ご撃数	打擊回数人	Ν			
			1/\	X		測定月日		0 ≀	10	20 ≀	数/貫		N値~深度図		
尺	度	厚	図	分	調	日	度	10	20	30	貫入量	値	I D 10 20 30 40 50 60		
E	0.35		<del>\(\frac{1}{1}\tau\)\(\frac{1}\tau\)\(\frac{1}{1}\tau\)\(\frac{1}\tau\)\(\fra</del>	表土											
2 2 3 3 4 5 5	1.30	0.95	00000 00000 00000	ローム	暗褐		1.15	3 /			3 /				
E 2	2.10	0.80		ローム	黄褐		1.45 2.15	1 /			30	3	3		
E	2.95			粘土	黄褐		2.45	30			30	1			
F 3	3.25		. 0 . 0 .	砂礫	暗褐灰	3.55	3.15	11 /			11 /				
E	3 90	0.65	//	粘土質細砂	暗褐灰		3.45	30			30	11			
E 4	0.00	0.00	0.0000000000000000000000000000000000000				4.15	41 / 30			41 / 30	41			
5			0.000	T-1- T-10-	暗褐灰		5.15 5.15	貫	入不	淵	50 / 0				
6				<b>砂</b> 镰	灰褐			50			50				
8	6.80	2.90	0.0.0.0.0.0.0.0				6.32	17			17	88.2	2		
E 7	7.40			細砂	褐灰		7.15	18 / 30			18 / 30	18	8		
Ē							7.45								
E 8							8.15	50 / 19			50 / 19	78.9			
E							8.34								
E 9							9.15	50 / 29			50 / 29	51.7	7		
E 10				細砂	暗緑灰		10.15	50			50				
10							10.38	23			23	65.2	2		
11							11.15	50 /			50 / 22	68.2			
Ē			······				11.37	22				08.2			
E 12	12.05 12.27	4.65	· · · · · · ·	中砂	暗緑灰		12.15	50 / 12			50 / 12	125	55		
							12.27								