

所在地 東京都新宿区北新宿二丁目14-6付近

位置情報については、おおよその位置を示したものとなります。

標準	深	層	柱	土質区分	色調	孔内水位／測定月日	標準貫入試験					N		
							深	10cmごとの打撃回数			打撃回数／貫入量			
								0	10	20				
尺	度	厚	図				度	10	20	30	値			
1		1.80	1.80	埋土	暗茶褐 黑白灰 暗茶灰	4/15 4.15	1.15				0 / 30	0		
2				粘土質シルト	暗茶灰		1.45			自沈			0.7	
3		3.15	1.35				2.15	1 / 45		1 / 45				
4				砂礫	茶灰 緑灰 暗茶灰 暗緑灰		2.60						20	
5							3.15			20 / 30				19
6							3.45	4	7	9 / 30				
7							4.15			19 / 30				
8							4.45	5	6	8 / 30				
9							5.15			37 / 30				
10		7.50	4.35	細砂	暗緑灰 暗灰		5.45	12	14	11 / 30			37	
11							6.15			12 / 5	50 / 25			60
12							6.40	13	25	5 / 25				
						7.15			22 / 9	50 / 29			51.7	
						7.44	14	14						
						8.15			50 / 20					
						8.35	19	31				75		
						9.15		11 / 1	50 / 11					
						9.26	39						136	
						10.15	50 / 9		50 / 9				167	
						10.24								
						11.15	50		50 / 10				150	
		12.23	4.73			11.25								
						12.15	50 / 8		50 / 8			188		
						12.23								