新宿区地盤資料

調査整理番号 024-029

所在地 東京都新宿区新宿三丁目 2 6 - 6 付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

<u>_</u>	:22			T	T	T	l	その位置を示したものとなります。							
票	深	層	柱	土	色	孔 内 水 位	深	1	0 cm の打	ت ش	‡T	N	標準貫入試験		
			状	質		小 位 /	1/1/	回	_	数	打撃回数/	1 N			
			1/\	X				0	10		数/貫		N値~深度図		
₹	度	厚	図	分	調	測定月日	度	10	≀ 20	30	λ	値	Ī		
Ì		,,	/	7.	Ar J						_		b 10 20 30 40 50		
				埋土	灰褐										
1	1.55	1.55													
2							2 15	1	1		2				
3 4 5 6			X	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	褐		2.15	1 / 17	1 / 14		31	1.9	9 9		
			0 0 0 0 0				3.15	1		1	3				
						4	3.49	18	1_	6	3 / 34	2.6	.el 🕈 📗		
			88888				4.15	1 / 1	1 / 9	2 / 12	4 / 34				
			XXXXX				4.49	13	9	12	34	3.5	5 \		
5			X	/			5.15	1 / 8	2 / 11	3 / 11	6 / 30	6	6		
6	5.70	4.15	77777				5.45	1	1						
- 6 - - - - 7					黄褐淡褐		6.15	1 / 18	1 / 12		2 / 30	2	2 1		
						7.60	7.15	1 /	1	1	3				
						7.60	7.45	12	1 / 9	1 / 9	3 / 30	3	3 7		
- - 8							8.15	. 1			1,				
							8.54	39			39	0.8	,		
9							9.15	1 / 17	1 / 6	1 / 7	3 / 30	2	3		
10 11 11							9.45		-	,		J			
							10.15	20	1		2 / 30	2	2		
	10.85	5.15					11.15				17				
			<i> </i>				11.45	5	6	6	30	17	17		
			://::::				12.15				13				
			<i>,</i>				12.45	5	4	4	30	13	13 /		
							13.15				10	40			
			[:::::::				13.45	2	4	4	30	10			
							14.15	4	4	4	12 / 30	12	12		
							14.45				12				
							15.15 15.45	4	4	4	30	12	12 •		
							16.15				12				
13 14 15 16 17 17 18 19 19 19 19 19 19 19 19 19 19 19 19 19	16.60	5.75	····/			1	16.45	4	4	4	30	12	12 •		
							17.15				16				
							17.45	4	6	6	30	16	6 1		
				砂質粘土 淡褐	Sylvam		18.15	6	6	6	18 / 30	18	ıa de la		
					淡褐		18.45								
							19.15	4	7	5	16 / 30	16	16		
							19.45 20.15				15				
	20.30	3.70	······			1	20.15	4	5	6	30	15	15 •		
21			::::; <i>;</i>				21.15				19		15		

