新宿区地盤資料

調査整理番号 029-059

所在地 東京都新宿区歌舞伎町一丁目 2 付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

標	深	層	柱	±	色	孔.	おおよその位直を示したものとなります。 											
	,*	7		質		内水位	深	1 ح	0 cn の打									
			状			业 / 測			10	<u>釵</u> 20	直数				N値~	深度図		
				X		/ 測定月日			1	貫入								
尺 :	度	厚	図	分	調	日	度	10	20	30	量	値	0 1	0 2	0 3	0 4	10 5	
																		-
1 2 3 4 5 6 7 7 10 11 11 12																		-
_ 2																		
- 3																		
- 4																		-
- 5																		
																		-
- 6																		
- 7					素掘													
-																		
- 8																		
9																		
- 10																		
- - 11																		
-																		
- 12																		
- 13																		
- 14	14.00	14.00		To SE Va I	**		14.00	30			17 / 30	17	,	٩				
-	14.60	0.60		砂質粘土	青灰		14.30								\			
- 15 -				砂質粘土	黄褐色		15.00 15.30	30			22 / 30	22			<i>b</i>			
- 16	16.05	1.45					16.00 16.10				50 / 10	150						
	16.90	0.85	0.0.0 0.00	砂礫	褐灰						4.							
17	10.90	. U.85					17.00	30			11 / 30	11		~				
- 18				粘土	青灰													
	18.65	1.75																
19				粘土	暗青灰		19.00	30			21 / 30	21		<u> </u>				
113 14 15 15 17 17 18 19 19 19 19 19 19 19 19 19 19 19 19 19	19.65	1.00		中砂	黄褐		19.30 20.00	50			50				_			
- 20 -	20.18	0.53	•••••	. ~	34 FM		20.00	18			18	83.3						