

所在地 東京都新宿区神楽坂三丁目2 - 36 付近

標尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値	
							深 度	10 cm ごと の打撃 数			打撃 回数 / 貫入量		
								0	10	20			
		0.70	0.70	盛土	暗茶褐	4.90	10	1	1	2	2	0	
1				ローム	茶褐		1.15	1	1	2	2	2	
							1.45	16	14	30			
2							2.15	1	1	2	2	2	
							2.45	15	15	30			
3							3.15			4	30		
							3.45	1	2	1	30		
4				4.15				6	30				
				4.45	2		2	2	30				
5				5.15				3	30				
				5.45	1		1	1	30				
6	5.90	5.20		砂礫	暗黄褐		6.15			4	30		
				6.45	1		1	2	30				
7	6.60	0.70		砂質粘土	茶褐		7.15			10	30		
							7.45	3	3	4	30		
8	7.70	1.10		粘土質細砂	暗黄褐		8.15			16	30		
							8.45	5	5	6	30		
9							9.15			27	30		
							9.45	9	9	9	30		
10	10.00	2.30				10.15			14	30			
						10.45	4	5	5	30			
11				細砂	暗黄灰	11.15			17	30			
						11.45	5	6	6	30			
12						12.15			20	30			
						12.45	6	7	7	30			
13						13.15			25	30			
						13.45	7	8	10	30			
14						14.15			30	30			
						14.45	7	10	13	30			
15				シルト	暗灰 暗緑灰	15.15			28	30			
						15.45	8	9	11	30			
16	15.90	5.90				16.15			11	30			
						16.45	3	4	4	30			
17						17.15			13	30			
						17.45	4	5	4	30			
18				砂礫	暗緑灰	18.15			11	30			
						18.45	3	4	4	30			
19	18.70	2.80				19.15	50		50	3			
						19.18	3						
20						20.15	50		50	2			
				20.17	2								
21				21.15	50		50	4					
					4								

