

所在地 東京都新宿区早稲田南町3-2-1 付近

標尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値	N 値 - 深度図
							深 度	10 cm ごと の打撃 数			打撃 回数 / 貫入量		
								0	10	20			
				埋土	灰 暗茶灰	3/27 1.80	1.15	1 / 30		1 / 30		0	
1	1.00	1.00		有機質ローム	暗茶灰		1.45					1	
2	2.10	1.10		凝灰質粘土	茶灰		2.15	1 / 30		1 / 30	1		
	2.70	0.60					2.45						
3				粘土	黄灰		3.15	1 / 14	1 / 9	3 / 33	2.7		
	3.60	0.90					3.48						
4							4.15			21 / 30	21		
							4.45	5	7	9	21		
5							5.15			28 / 30	28		
							5.45	3	6	19	28		
6							6.15	32	18 / 3	50 / 13	115		
						6.28							
7				砂礫	黄褐	7.15	23	17	10 / 5	60			
						7.40			50 / 25				
8						8.15	24	26 / 9	50 / 19	78.9			
						8.34							
9						9.15	50 / 8		50 / 8	188			
						9.23							
10						10.15	30	20 / 5	50 / 15	100			
						10.30							
11	11.20	7.60				11.15	50 / 5		50 / 5	300			
						11.20							