

所在地 東京都新宿区若松町 3 3 - 9 付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	10 cmごとの打撃回数					N 値	標準貫入試験				
							深 度	10 cmごとの打撃回数			打撃回数 / 貫入量		N 値 - 深度図				
								0	10	20							
	0.50	0.50		盛土	茶褐												
1							1.15				5 / 30						
2							1.45	1	2	2	4 / 31						
3				ローム	茶褐		2.15	1 / 8	2 / 15	1 / 8	4 / 31						
4							2.46										
5							3.15			2 / 14	4 / 34						
6							3.49	1	1								
7							4.15				3 / 30						
8							4.45	1	1	1							
9							5.15	1 / 12	1 / 16	1 / 11	3 / 39						
10							5.54										
11							6.15		1 / 8	2 / 14	4 / 32						
12							6.47	1									
13							7.15	1 / 8	1	3 / 16	5 / 34						
14							7.49										
15				火山灰質粘土	茶褐 茶褐灰		8.15				6 / 30						
16							8.45	2	2	2							
17							9.15				6 / 30						
18							9.45	2	2	2							
19							10.15				6 / 30						
20							10.45	2	2	2							
21							11.15				7 / 30						
22							11.45	2	2	3							
23							12.15				9 / 30						
24							12.45	3	3	3							
25							13.15				14 / 30						
26							13.45	3	4	7							
27							14.15				13 / 30						
28							14.45	4	4	5							
29							15.15				37 / 30						
30							15.45	10	15	12							
31							16.15				39 / 30						
32							16.45	12	13	14							
33							17.15				42 / 30						

[illegible]