

所在地 東京都新宿区百人町一丁目18-11付近

標	深	層	柱	土	色	孔内水位／測定月日	標準貫入試験					N
							深	10 cmごとの打撃数			打撃回数／貫入量	
								0	10	20		
尺	度	厚	状	質	調		度	10	20	30	値	
		0.60	0.60	盛土	褐							
1							1.15	1 / 7	2 / 13	2 / 30	5	
2							1.45					
3							2.15	1 / 8	1 / 8	2 / 14	4	
4							2.45					
5							3.15	1 / 14	1 / 8	3 / 32	2.8	
6							3.47					
7							4.15	1 / 12	1 / 8	3 / 30	3	
8							4.45					
9							5.15			3 / 30	3	
10							5.45	1 / 1	1 / 1	1 / 30	3	
11							6.15	1 / 20	1 / 20	2 / 40	1.5	
12							6.55					
13							7.15	0 / 20	1 / 20	1 / 30	1	
14							7.45					
15							8.15	1 / 15	1 / 1	3 / 35	2.6	
16							8.50					
17							9.15	12 / 15	13 / 13	40 / 30	40	
18							9.45					
19							10.15	12 / 12	13 / 13	38 / 30	38	
20							10.45					
21							11.15	12 / 12	14 / 11	37 / 30	37	
22							11.45					
23							12.15	11 / 9	6 / 6	26 / 30	26	
24							12.45					
25							13.15	6 / 6	6 / 6	18 / 30	18	
26							13.45		23 / 5	50 / 15	100	
27							14.15	27 / 27				
28							14.30					
29							15.15	24 / 24	26 / 26	50 / 20	75	
30							15.35					
31							16.15	10 / 10	20 / 5	50 / 25	60	
32							16.40					
33							17.15	7 / 7	7 / 11	25 / 30	25	
34							17.45					
35							18.15	7 / 7	11 / 11	29 / 30	29	
36							18.45					
37							19.15	7 / 7	8 / 10	25 / 30	25	
38							19.45					
39							20.15	7 / 7	9 / 10	26 / 30	26	
40							20.45					
41							21.15				29	

