

所在地 東京都新宿区西早稲田一丁目 1 - 1 5 付近

標	深	層	柱	土	色	孔内水位 / 測定月日	標準貫入試験							
							深	10 cmごとの打撃数			打撃回数 / 貫入量	N		
								0	10	20				
尺	度	厚	状	質	調		度	10	20	30	値			
	0.40	0.40	盛土											
1			ローム	茶褐			1.15	2		2	1.9			
							1.47			32		32	1.0	
2							2.15	1	1	31		31	2.0	
							2.46						2.8	
3							3.15	2	2	30		30	3.0	
							3.45						4.6	
4			砂礫	暗黄灰			4.15	3	3	46				
							4.47			32		32	33	
5							5.15	3	3	30		30	20	
							5.45						17	
6	5.60	5.20					6.15	46	46	30		30	107	
							6.45						27	
7			粘土質細砂	黄灰			7.15	33	33	29				
							7.45			30		30	31	
8							8.15	20	20	30		30	33	
							8.45						29	
9							9.15	17	17	30		30	31	
							9.45						33	
10	9.80	2.90	砂礫	暗黄灰			10.15	50	50	107				
							10.29			14		14	27	
11							11.15	27	27	30		30	29	
							11.45						31	
12							12.15	29	29	30		30	33	
							12.45						39	
13			硬質粘土	青灰			13.15	31	31	39				
							13.45			30		30		
14							14.15	33	33	30		30		
							14.45							
15	15.45	4.75					15.15	39	39	30		30		
							15.45							