

所在地 東京都新宿区中落合一丁目17-1付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位／測定月日	標準貫入試験				N 値	N 値～深度図	
							深 度	10 cm ごとの打撃回数					打撃回数／貫入量
								0	10	20			
1		1.50	1.50	埋土	黒褐色	2.60	1.15	2 / 30		2 / 30		2	
2	2.15	0.65	礫混じり粘土	茶褐色	1.45						3		
	2.55	0.40	粘土	褐灰色	2.15		3 / 30		3 / 30		3		
3					2.45								
					3.15		50 / 23		50 / 23	65.2			
4				砂礫	褐灰色		3.38						
					4.15		50 / 30		50 / 30	50			
5					4.45								
	5.60	3.05			5.15		50 / 27		50 / 27	55.6			
6					5.42								
7					6.15	50 / 25		50 / 25	60				
					6.40								
8				細砂	緑灰色 暗緑灰色	7.15	50 / 23		50 / 23	65.2			
					7.38								
9					8.15	50 / 17		50 / 17	88.2				
					8.32								
10					9.15	50 / 24		50 / 24	62.5				
	10.43	4.83			9.39								
					10.15	50 / 28		50 / 28	53.6				
					10.43								