

所在地 東京都新宿区中落合一丁目20-3付近

標高	深度	層厚	柱状図	土質区分	色調	孔内水位 / 測定月日	標準貫入試験					N値	N値 - 深度図
							深さ	10 cmごとの打撃回数			打撃回数 / 貫入量		
								0	10	20			
1	1.15	1.15	盛土		暗褐	1/29 3.20	1.15				8 / 30	8	
2	1.45				3 / 3		2 / 30	8					
3	2.15	7	12	14	33 / 30		33						
4	2.45				33 / 30		33						
5	3.15	14	15	21	50 / 30		50						
6	3.45				50 / 30		50						
7	4.15				12 / 30		12						
8	4.45	3	4	5	15 / 30		15						
9	5.15	4	4	7	43 / 30		43						
10	5.45				43 / 30		43						
11	6.15	9	13	21	50 / 30	50							
12	6.45				50 / 30	50							
13	7.15	12	16	22	53.6 / 28	53.6							
14	7.45				53.6 / 28	53.6							
15	8.15	15	19	8	50 / 25	60							
16	8.43	16	22	5	50 / 16	93.8							
17	9.15	34	6		40 / 30	40							
18	9.40	9	15	16	36 / 30	36							
19	10.15	8	13	15	34 / 30	34							
20	10.31				62.5 / 24	62.5							
21	11.15	12	27	4	51.7 / 29	51.7							
22	11.45				51.7 / 29	51.7							
23	12.15	11	17	22	50 / 30	50							
24	12.45				50 / 30	50							
25	13.15	8	11	15	100 / 15	100							
26	13.45				100 / 15	100							
27	14.15	12	27	4	60 / 25	60							
28	14.39				60 / 25	60							
29	15.15	14	21	5	75 / 20	75							
30	15.44				75 / 20	75							
31	16.15	11	17	22									
32	16.45												
33	17.15	32											
34	17.30												
35	18.15	14	21	5									
36	18.40												
37	19.15	24	26										
38	19.35												