

所在地 東京都新宿区中落合一丁目21-3付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	10 cm ごと の打撃数					N 値	標準貫入試験 N 値 - 深度図
							深 度	打撃回数			打撃回数 / 貫入量		
								0 10	10 20	20 30			
1	1.60	1.60		暗褐 黄褐	9/7 2.95	1.15	7	7	8	22 / 30	22		
2	1.45							30 / 30	30				
3	2.15	8				11	11	30 / 30	39				
4	2.45							39 / 30	83.3				
5	3.15	11	13	15	50 / 18	107							
6	3.45				50 / 14	55.6							
7	4.15	19	31 / 8		50 / 27	62.5							
8	4.33				50 / 24	93.8							
9	5.15	32	18 / 4		50 / 16	78.9							
10	5.29				50 / 13	115							
11	6.15	17	21	12 / 7									
12	6.42												
13	7.15												
14	7.39	18	19	4									
15	8.15	21	29 / 6										
16	8.31												
17	9.15	20	30 / 9										
18	9.34												
19	10.15	37	13 / 3										
20	10.28												