

所在地 東京都新宿区西落合一丁目21-22付近

標	深	層	柱	土	色	孔内水位 / 測定月日	標準貫入試験					N		
							深	10 cm ごと の打撃数			打撃 回数 / 貫入量			
								0	10	20				
尺	度	厚	状	質	調		度	10	20	30	値			
	0.70	0.70		埋土	黒褐						0			
1				凝灰質粘土	褐灰	4.30 	1.15				0.5			
							1 / 55		1 / 55					
2							2.15	0	1	2	3 / 30	3		
							2.45							
3	3.00	2.30		砂礫	暗褐灰		3.15			12 / 6	50 / 26	57.7		
							3.41	20	18					
4							4.15				35 / 30	35		
							4.45							
5							5.15	21	29		50 / 20	75		
							5.35							
6							6.15	50			50 / 10	150		
							6.25							
7							7.15	28	22 / 7		50 / 17	88.2		
							7.32							
8				シルト	暗灰			8.15			10 / 30	10		
								8.45	3	3	4			
9	9.10	1.35		シルト質細砂	暗灰		9.15			25 / 30	25			
							9.45	7	10	8				
10	10.00	0.90		シルト	暗灰		10.15			7 / 30	7			
							10.45	3	2	2				
11	10.60	0.60		砂質シルト	暗灰		11.15			36 / 9	50 / 29	51.7		
							11.44	6	8					
12				礫混り細砂	暗褐		12.15			17 / 7	50 / 27	55.6		
							12.42	18	15					
13				砂礫	暗黄褐		13.15			18 / 5	50 / 15	100		
								13.30	32					
14								14.15				6 / 3	50 / 23	65.2
								14.38	26	18				
15								15.15	50			50 / 10	150	
								15.25						
16	16.26	3.71					16.15			9 / 1	50 / 11	136		
							16.26	41						