

所在地 東京都新宿区西落合三丁目29-1付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験						
							深 度	10 cmごとの打撃回数			打撃回数 / 貫入量	N 値	
								0 ~ 10	10 ~ 20	20 ~ 30			
0.70	0.70			埋土	暗褐灰	5.70	1.15				6 / 30	6	
1				暗茶褐	1.45								6
2					2.15						4 / 30	4	
3					2.45		1	1	2		4 / 30	4	
4					3.15						4 / 30	4	
5					3.45		1	1	2		4 / 30	4	
5.60	4.90				4.15					4 / 30	4		
6				凝灰質粘土	4.45		1	1	2		4 / 30	4	
7					5.15						5 / 30	5	
8					5.45		1	2	2		30	1	
9					6.15	1 / 30				1 / 30	1		
7.50	1.90				6.45						1		
8				粘土	7.15	1 / 30				1 / 30	1		
9					7.45							3	
10					8.15					3 / 30	3		
9.70	2.20				8.45	1	1	1		30	4		
10.45	0.75			粘土混り細砂	9.15				4 / 30	4			
					9.45	1	1	2		30	11		
					10.15				11 / 30				
					10.45	3	3	5		30			