

所在地 東京都新宿区西落合三丁目 1 - 4 付近

標	深	層	柱	土	色	孔内水位 / 測定月日	標準貫入試験					N	N 値 - 深度図		
							深	10 cm ごと の打撃数			打撃 回数 / 貫入量				
								0	10	20					
尺	度	厚	状	質	調		度	10	20	30		値			
1			ローム	暗茶褐			1.15	1 / 20	1 / 11		2 / 31	1.9			
2							1.46							2.7	
3							2.15	1 / 16	1 / 7	3 / 33	3.8				
4	3.60	3.60					3.15	1 / 13	1 / 7	2 / 12	4 / 32	2.4			
5			火山灰質粘土	黄褐			3.47				2 / 25	1.7			
6							4.15	1 / 1	1 / 15		2 / 35	3.4			
7							4.40					4			
8			粘土	乳黄灰 乳灰 乳黄灰			5.15	1 / 20	1 / 15		2 / 35	3.9			
9							5.50			2 / 15	4 / 35	5			
10							6.15	1 / 1	1 / 15		4 / 30	17			
11							6.50					51.7			
12			粘土	淡青			7.15	1 / 12	1 / 8		4 / 30	100			
13							7.45					115			
14							8.15		2 / 14	1 / 7	4 / 31	50			
15							8.46	1 / 1	2 / 2	2 / 30		50			
16			砂礫	青灰			9.15	1 / 1			5 / 30	50			
17							9.45					51.7			
18							10.15	2 / 2	3 / 12		17 / 30	100			
19							10.45					115			
20							11.15			19 / 9	50 / 29	50			
21							11.44	14 / 28	17 / 5		50 / 15	50			
22							12.15					50			
23							12.30					50			
24							13.15		14 / 36		50 / 13	50			
25							13.28					50			
26							14.15	12 / 12	14 / 24		50 / 30	50			
27							14.45					50			
28							15.15			20 / 14	50 / 9	50			
29							15.44	14 / 13	16 / 22		50 / 30	50			
30							16.15					50			
31							16.45	13 / 13	15 / 15		50 / 30	50			