

所在地 東京都新宿区中井一丁目9-17付近

標尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位／測定月日	標準貫入試験					N 値	N 値～深度図	
							深 度	10 cmごとの打撃回数			打撃回数／貫入量			
								0	10	20				
	0.30	0.30		埋土 (礫混じり粘性土)	茶褐灰	4/12 2.80						0		
1	1.10	0.80		埋土 (砂礫)	黄褐		1.15				9		9	
2	2.60	1.50		固結凝灰質シルト	淡褐灰		1.45	2	3	4	30	18	18	
3							2.15	5	6	7	30	41	41	
4				砂礫	黄褐灰		2.45					44	44	
5							3.15	11	14	16	30	45	45	
6							3.45					50	75	
7							4.15	14	15	15	30	50	93.8	
8							4.45					50	78.9	
9							5.15	15	13	17	30	50	88.2	
10							5.45					50	100	
11						6.15	20	30		20	50	88.2		
	11.32	8.72				6.35					50			
						7.15	30	6		16	50			
			7.31					50						
			8.15	25	25	9	19	50						
			8.34					50						
			9.15	29	21	7	17	50						
			9.32					50						
			10.15	23	27	5	15	50						
			10.30					50						
			11.15					50						
			11.32	22	28	7	17	50						