

所在地 東京都新宿区北新宿三丁目26-19付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	10 cmごとの打撃回数				N 値	標準貫入試験	
							深 度	10 cmごとの打撃回数					打撃回数 / 貫入量
								0	10	20			
1	1.10	1.10		埋土	暗褐		1.15			3 / 30	3		
2	2.70	1.60		ローム	茶褐		1.45	1	1	1 / 30	3		
3				凝灰質粘土	乳黄灰褐		2.15	1 / 11		1 / 9	3 / 30	2.8	
4	4.20	1.50		シルト質砂礫	暗黄灰		2.45					29	
5	5.00	0.80		シルト質微細砂	暗黄灰褐		3.15	1 / 12	1	1 / 32	3	13	
6				シルト混り砂礫	暗黄灰褐		3.47				29 / 30	17	
7	7.00	2.00					4.15	2	12	15 / 30	62.5	250	
8							4.45				13 / 30	150	
9							5.15				17 / 30	136	
10							5.45	4	4	5 / 30	71.4	107	
11							6.15				50 / 30		
12	12.29	5.29					6.45	4	6	7 / 30			
							7.15	12	23	4 / 24			
							7.39	50 / 6		50 / 6			
							8.15				50 / 10		
							8.21				50 / 11		
							9.15	50					
							9.25						
							10.15	40	10 / 1				
							10.26				2 / 1		
							11.15	28	20	1 / 21			
							11.36				50 / 14		
							12.15	25	25 / 4				
							12.29						