

所在地 東京都新宿区北新宿四丁目19-3付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位 / 測定月日	標準貫入試験					N 値	N 値 - 深度図	
							深 度	10 cm ごと の打撃 回数			打撃 回数 / 貫入 量			
								0 10	10 20	20 30				
	0.50	0.50		盛土	暗灰	3.80								
1	1.40	0.90		旧表土	黒灰		1.15	1 / 12	1 / 11	3 / 33	2.7			
	1.80	0.40		ローム質粘土	黄灰		1.48							
2				粘土	黄灰		2.15	1 / 40		1 / 40	0.8			
	2.90	1.10												
3														
4				砂礫	茶褐		3.15			32 / 30	32			
							3.45	7	11	14	40 / 30	40		
5							4.15	11	13	16	50 / 15	100		
							4.45				50 / 20	75		
6							5.15	30	20 / 5		52 / 20	78		
							5.30				35 / 30	35		
7							6.15					30		
							6.35	22	28					
8							7.15	26	26					
						7.35								
9	8.70	5.80		硬質シルト	淡青	8.15	7	13	15					
	9.45	0.75				8.45								
						9.15			30 / 30					
						9.45	6	10	14					