

所在地 東京都新宿区北新宿四丁目23付近

標尺	深度	層厚	柱状図	土質区分	色調	孔内水位 / 測定月日	標準貫入試験					
							深 度	10 cmごとの打撃回数			打撃回数 / 貫入量	N 値
								0 10	10 20	20 30		
	0.80	0.80		盛土	暗褐	1.84	1.15	1 / 32	1 / 32	0.9		
1	1.70	0.90		凝灰質粘土	黄褐		1.47					
2				砂礫	黄褐		2.15	15	17	18 / 29	50 / 29	51.7
3							2.44					
4							3.15	20	30		50 / 20	75
5							3.35					
6							4.15				50 / 30	50
7							4.45	19	13	18	30	
							5.15		23 / 6		50 / 16	93.8
							5.31					
							6.15	16	20	14 / 4	50 / 24	62.5
							6.39					
	7.25	5.55					7.15		50 / 10	150		
							7.25					