

所在地 東京都新宿区西新宿一丁目 1 1 - 4 付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔 内 水 位 / 測 定 月 日	標準貫入試験					N 値	N 値 - 深度図
							深 度	10 cm ごとの打撃回数			打撃回数 / 貫入量		
								0	10	20			
	0.40	0.40		表土	暗茶褐								
1							1.15	2 / 12	5 / 32	4.7			
2							1.47						
3							2.15	2 / 14	1 / 6	4			
4							2.45						
5							3.15	1 / 17	1 / 9	3 / 8	2.6		
6							3.49						
7							4.15	1 / 15	1 / 7	3 / 32	2.8		
8							4.47						
9							5.15	1 / 13	1 / 1	3 / 30	3		
10							5.45						
11							6.15		2 / 15	1 / 7	4 / 32	3.8	
12							6.47	1					
13							7.15	1 / 15	1 / 15	2 / 30	2		
14							7.45						
15							8.15	1 / 16	1 / 15	2 / 31	1.9		
16							8.46						
17							9.15	1 / 18	1 / 15	2 / 33	1.8		
18							9.48						
19							10.15	1 / 26	1 / 15	2 / 41	1.5		
20							10.56						
21							11.15	1 / 20	1 / 14	2 / 34	1.8		
22							11.49						
23							12.15	1 / 17	1 / 13	2 / 30	2		
24							12.45						
25							13.15			12 / 30	12		
26							13.45	3	4	5	13		
27							14.15			13 / 30	13		
28							14.45	4	4	5	12		
29							15.15			12 / 30	12		
30							15.45	4	4	4	16		
31							16.15			16 / 30	16		
32							16.45	4	5	7	18		
33							17.15			18 / 30	18		
34							17.45	4	6	8	18		
35							18.15			18 / 30	18		
36							18.45	4	6	8	23		
37							19.15			23 / 30	23		
38							19.45	6	7	10	21		
39							20.15			21 / 30	21		
40							20.45	6	7	8			
41							21.15			24			

