

所在地 東京都新宿区西新宿一丁目3 - 1 4 付近

標	深	層	柱	土	色	孔内水位 / 測定月日	標準貫入試験					N	N値 - 深度図	
							深	10 cmごとの打撃数			打撃回数 / 貫入量			
								0	10	20				
尺	度	厚	状	質	調		度	10	20	30		値		
1						6/22 5.20								
2														
3														
4														
5														
6	5.45	5.45	粘土質ローム	茶褐色										
	5.75	0.30												
7	6.25	0.50	砂混り粘土	黄灰褐色	6.15		0 / 3	1 / 7	3 / 22	4 / 32	3.8			
8			粘土質細砂	黄褐色	6.47						3.8			
	7.15							7.15	1 / 15	1 / 7	4 / 32			
9	7.60	1.35	粘土質微粒砂	黄褐色	7.47						8			
	8.15							8.15	2 / 12	2 / 8	8 / 30			
10	8.75	1.15			8.45						15			
	9.15							9.15	4 / 5	6 / 6	15 / 30			
11			粘土混り細砂	黄褐色	9.45						10			
	10.15							10.15	2 / 3	5 / 5	10 / 30			
12	11.80	3.05			10.45						11			
	11.15							11.15	3 / 3	5 / 5	11 / 30			
13	12.60	0.80	細砂	黄褐色	11.45						16			
	12.15				12.15		5 / 5	6 / 6	16 / 30					
14	13.95	1.35	レキ混り細砂	黄褐色	12.45						18			
	13.15				13.15	5 / 5	8 / 8	18 / 30						
15			砂レキ	黄褐色	13.45					100				
	14.15						14.15	33 / 8	60 / 18					
16	15.15				14.33					69.2				
	15.15						15.15	15 / 23	22 / 6	60 / 26				
17	16.15				15.41					80				
	16.15						16.15	10 / 30	24 / 4	64 / 24				
18	17.15				16.39					180				
	17.15						17.15	60 / 10						
19	18.15		シルト	暗灰色	17.25					11				
	18.15						18.15	3 / 3	5 / 30					
20	19.15				18.45					12				
	19.15						19.15	4 / 11	4 / 9	12 / 30				
21	20.15				19.45					44				
	20.15						20.15	6 / 10	28 / 30					
22	20.45				20.45									
	21.15						21.15	15 /	60 /					

