

所在地 東京都新宿区西新宿一丁目16-2付近

標 尺	深 度	層 厚	柱 状 図	土 質 区 分	色 調	孔内水位／測定月日	標準貫入試験					N 値	N 値～深度図	
							深 度	10 cm ごとの打撃回数			打撃回数／貫入量			
								0 〃	10 〃	20 〃				
0	0.60	0.60		盛土										
1							1.15				8 / 30			
2							1.45	3	3	2	5 / 30			
3							2.15	1	2	2	5 / 30			
4							2.45							
5							3.15			1 / 12	3 / 32			
6							3.47	1	1					
7							4.15	1 / 13	2	2	5 / 33			
8							4.48							
9							5.15				5 / 30			
10							5.45	1	2	2	5 / 30			
11	10.80	10.20					6.15	2 / 15	2 / 16		4 / 31			
12	11.70	0.90					6.46							
13							7.15	1 / 14	2 / 16		3 / 30			
14							7.45							
15							8.15	1 / 19	1 / 13		2 / 32			
16							8.47							
17							9.15	1 / 21	1 / 15		2 / 36			
18							9.51							
19	19.60	7.90					10.15	1 / 19	1 / 14		2 / 33			
20							10.48							
21							11.15	3 / 12	2 / 8	2	7 / 30			
22							11.45							
23							12.15				19 / 30			
24							12.45	5	6	8	19 / 30			
25							13.15				32 / 30			
26							13.45	10	11	11	32 / 30			
27							14.15				21 / 30			
28							14.45	6	7	8	21 / 30			
29							15.15				23 / 30			
30							15.45	7	7	9	23 / 30			
31							16.15				24 / 30			
32							16.45	8	7	9	24 / 30			
33							17.15				20 / 30			
34							17.45	6	6	8	20 / 30			
35							18.15				22 / 30			
36							18.45	7	6	9	22 / 30			
37							19.15				33 / 30	</		

