新宿区地盤資料

調査整理番号 147-031

所在地 東京都新宿区西新宿三丁目 8 付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

-ar-	200		1			1		その位置を示したものとなります。								
漂	深	層	柱	土	色	孔内	1 1 0 0		0 cm	Z Er	標準貫入試験 標準貫入試験					
			状	質		水位	深	回		数	打擊回数	IN				
			1/	×		/ 測 定			10		I数/貫		N値~深度図			
₹	度	厚	図	分	調	測定月日	度	≀ 10	² 20	30	λ	値				
Ì													D 10 20 30 40 50			
1	0.90	0.90	l //	埋土	灰褐			,		,	•					
	1.60	0.70		表土	暗茶褐		1.15	1 / 15	1 / 9	1 / 6	3 / 30	3	•			
3			00000 00000				2.15	2 /	2 / 15		4					
							2.46	16	15		31	3.9				
- 3			00000	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	茶褐	6/4 4.20	3.15	2 / 18	2 / 14		4 / 32	3.8				
4			XXXX				3.47				4					
	4.60	3.00		X			4.15	2 / 17	2 / 13		30	4	4 7			
- 5					茶褐		5.15	1	1 /		2 /					
				粘土質ローム			5.49	21	13		34	1.8				
- 6							6.15	1 / 31			1 / 31	1.0	J.			
- 7	6.90	2.30	TYSK!!!	,			6.46				1					
				粘土	黄乳		7.15	1 / 30			, 30	1	1 <mark>†</mark>			
- 8							8.15	1			1 /					
							8.48	33			33	0.9	•			
- 9							9.15	1 / 30			1 / 30	1				
7 8 9							9.45 10.15	1			1					
							10.50	35			, 35	0.9	 			
							11.15	/ /	1 /		2 /					
							11.47	19	13		32	1.9				
- 1	12.55	5.65					12.15	16	1 / 14		2 / 30	2				
				細花少	黄褐 "茶褐		12.45				15					
							13.45	3	5	7	30	15				
- 14							14.15	4	6	10	20 / 30	20				
15							14.45	7	J	10		20				
						11	15.15 15.45	5	10	12	27 / 30	27				
- 16			······				16.15				29					
=	16.05						16.45	6	10	13	30	29				
13 14 15 16 17 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	18.45	4.40		- 粘土 - 黄乳 - 砂質シルト - 暗灰		1	17.15	3	5	6	14 / 30	14				
		1.50			黄乳		17.45 18.15				12					
					暗灰	-	18.45	4	5	3	30	12				
							19.15				4					
						2	19.45	1	1	2	30	4				
							20.15	1 / 15	1 / 15		2 / 30	2				
- 21							20.45 21.15				4					

