


新宿区地盤資料

調査整理番号 149-036

所在地 東京都新宿区西新宿五丁目 8 - 5 付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。
位置情報については、おおよその位置を示したものとなります。



				145 030(-) 105) (2/2										
21	21.50	2.00		微細砂	暗青灰	20.65	50 / 22	50 / 22	68.2					
22				硬質粘土	暗青灰	21.65	50 / 22	50 / 22	68.2					
23	23.20	1.70				21.87								
24				粗砂	暗青灰	22.65	50 / 21	50 / 21	71.4					
25	25.24	2.04				22.86								
						23.65	50 / 15	50 / 15	100					
						23.80								
						24.65	50 / 16	50 / 16	93.8					
						24.81								
						25.65	50 / 19	50 / 19	78.9					
						25.84								