新宿区地盤資料

調査整理番号 151-093

所在地 東京都新宿区西新宿七丁目 1 5 - 1 付近

この資料は区内で建築されるための地盤の状況を確認するための参考資料です。 位置情報については、おおよその位置を示したものとなります。

票	深	層	柱	±	色	孔							標準貫入試験
			状	質		内 水位 /	深	回	10cmご との打撃 回 数 回		打撃回数/貫	N	1
			-70	区		測定月日		0	10 ≀	20	数/貫		N 値~深度図
₹	度	厚	図	分	調	月日	度	10	20		lλ	値	5 D 10 20 30 40 50
	0.70	0.70	l //	1 埋土	暗褐								
1	0.70	0.70					1.15				6 /		
						7/11	1.45	2	2	2	30	6	6 1
2			XXXXX 00000			2.36	2.15	1	2	2	5 / 30	5	5
3							2.45 3.15	2			4		
				п-4	茶褐		3.50	/ 15	1	1	/ 35	3.4	.4 f
4			ÄÄÄÄÄÄ				4.15	1	1	1	3 / 30	3	
5			XXXXX				4.45			·			
			XXXXX XXXXX				5.15	1	2	2	5 / 30	5	5
6	6 25	E 65	XXXXX 00000				6.15	1 /	1 /		2 /		
İ	0.33	3.00					6.47	17	15		32	1.9	.9
7							7.15	1 / 16	1 / 15		2 / 31	1.9	.g
8				凝灰質粘土	暗黄褐		7.46 8.15				6		
					暗乳褐		8.45	2	2	2	30	6	6 }
9							9.15	2	2	1	5 / 30	5	
	9.75	3.40		•			9.45			'		,	
- 1	10.60	0.85		砂質粘土	暗黄褐		10.15	2	3	4	9 / 30	9	g
1							11.15				10		
11							11.45	3	3	4	30	10	10
12				細砂	暗褐灰		12.15	5	6	6	17 / 30	17	17
13							12.45 13.15				12		
	13.80	3.20					13.45	4	5	3	30	12	12
14	.5.00	3.20	====				14.15	1	1	1	3 /	~	
إ							14.45				30	3	3
0							15.15	2	3	4	9 / 30	9	9
16							16.15				8 /		
							16.45	1	2	5	30	8	8 •
7							17.15	2	3	3	8 / 30	8	8 •
18				シルト	暗灰		17.45 18.15				11		
							18.45	4	3	4	30	11	11
19							19.15		_	_	15 /	,-	45
			====				19.45		5	5	30	15	
13 14 15 16 17 18							20.15	4	4	4	12 / 30	12	12
21							21.15				10		

_				1	1				i i	/				15	1-093	(力549)	(2/2)
E						20.45	4	4	4	30	12	2	,				=
21						21.15				10			-				
E						21.45	3	3	4	30	10	0					
21	21.90	8.10	0.0.0			22.15	30	20 / 6		50 / 16	93.8						
E			0.0.0			22.31	50			50	55.0	1					
23			0000			23.00 23.05	5			5	300					\rightarrow	
24			0.000				50			50 /							
24			0.000		暗灰	24.00 24.04	4			4	375_						
F			0.0.0	砂礫	暗褐灰		50			50 /							
25			0.0.0			25.00 25.04	4			4	375	5				-	
26			0.000				50			50							
26						26.00 26.07	7			7	214	1				-	
Ė			0.000				50 /			50 /							
27	27.03	5.13	.0.0.			27.00 27.03	3			3	500					 	
E																	