

所在地 東京都新宿区西新宿八丁目 1 - 1 0 付近

標	深	層	柱	土	色	孔内水位 / 測定月日	標準貫入試験					N	N値 - 深度図	
							深	10 cmごとの打撃回数			打撃回数 / 貫入量			
								0	10	20				
尺	度	厚	図	質	調		度	10	20	30		値		
		0.80	0.80	盛土	暗褐	4.00							0	
1							1.15		2	1	4			4
							1.45	1	14	6	30			
2							2.15	1	14	6	30			4
							2.45							
3							3.15					3		3
							3.45	1	1	1	30			
4				ローム	茶褐		4.15		2	1	4			4
							4.45	1	14	6	30			
5							5.15	2		2	6		5.8	
							5.46	13	2	8	31			
6							6.15		2	1	4			4
						6.45	1	14	6	30				
7		7.40	6.60			7.15	1	1		3		2.6		
						7.49								
8						8.15				6			6	
						8.45	2	2	2	30				
9						9.15					7		7	
						9.45	2	2	3	30				
10				粘土	黄褐 淡青灰	10.15		2	1	4		4		
						10.45	1	14	6	30				
11						11.15					6		6	
		11.70	4.30			11.45	2	2	2	30				
12				シルト混じり細砂	暗青灰	12.15	2	1	3	6		5.6		
						12.47	15	5	12	32				
13		13.15	1.45			13.15				14		14		
				細砂	青灰	13.45	4	5	5	30				
14		14.40	1.25			14.15				16		16		
						14.45	5	5	6	30				
15				砂質シルト	暗灰	15.15	2	1	1	4		4.3		
		15.50	1.10			15.43	15	7	6	28				
16		16.10	0.60	シルト混じり細砂	暗青灰	16.15		2	1	4		4		
				シルト	暗灰	16.45	1	14	6	30				
17		17.00	0.90			17.15		2	1	4		3.9		
						17.46	1	15	6	31				
18				粘土	黄灰	18.15					6		6	
		18.70	1.70			18.45	2	2	2	30				
19				礫混じり細砂	青灰	19.15				25		25		
		19.50	0.80			19.45	6	7	12	30				
20				砂礫	青灰	20.15			17	50		55.6		
		20.95	1.45			20.42	15	18	7	27				
21						21.15			20	50				

[illegible]